



RENAULT SPORT
INFORMATION NOTE N°1

CLIO CUP

REFERENCE	NI_2011_X85CUP_01
DATE	8 th March 2011
SUBJECT	defectives CBNT

We would like to inform you that some brand new cars, manufactured in Alpine Workshop between November 2010 and February 2011, present problems with lighting on the right side of the car (both headlight and rear light).

Indeed, it happens randomly that the right lighting doesn't work. The problem has been identified as due to CBNT (black electronic fuse box situated in the cockpit on the central canal, just under the instrument panel)

If you observed this lighting problem on the right side of the car, **and only in this case**, we kindly ask you to send back the CBNT for an update to XAP (CBNT Manufacturer) to the following address:

XAP Electronics
François Hardy / Samir Alimoussa
Le Mercure / bâtiment A
1740 avenue du Marechal Juin
30000 Nîmes (France)

More over, every shipment to XAP **must** to be accompanied with the following return form, indicating your details for the shipment back

We would like to apologize for the inconvenience

Renault Sport Technologies
Motorsport Department





RENAULT SPORT
RETURNS FORM



* Mandatory fields

1 - DATE PARTS SENT *	
------------------------------	--

2 – PARTS INFORMATION

Type of part *		Owner *	
N° of part *		Supplier *	

3 – PARTS HISTORY

Date of purchase *	
Usage (<i>approximate time period or mileage</i>)	
Details of previous work or repairs (<i>dates, reasons, work carried out...</i>)	

4 – DETAILS OF MALFUNCTION

Date *	
Description of problem *	
Number of incidents of the same type experienced on the same car or on other cars of the team *	
Other notes	

5 – RENAULT SPORT INFORMATION *

Subsidiary		Account N° at Dieppe	
------------	--	----------------------	--

6 – SIGNATURES *

Entrant		Renault Sport	
---------	--	---------------	--

